# **Interact for Lexmark**

## **Release Notes**

Version: 3.7.x

Compatible with ImageNow, Version 6.7.x and Perceptive Content,

Version 7.x

Written by: Embedded Solutions, R&D

Date: September 2016



# **Table of Contents**

nteract for Lexmark (May 10, 2015)	4
Overview	
Enhancements	
Associated Files	
Requirements	
Device Support	2

## Interact for Lexmark (May 10, 2015)

#### Overview

Interact for Lexmark is an embedded solution that can be installed on printers that support the Lexmark Embedded Solutions Framework (eSF). Interact for Lexmark enables Lexmark printers to integrate with Enterprise Software's Perceptive Content solution. It allows users to scan and index documents from the printer and route them directly to Perceptive Content (formerly ImageNow), which makes the documents available for retrieval and workflow processing.

#### **Enhancements**

This release enables Lexmark MFPs to integrate with Perceptive Content through Perceptive Integration Server, instead of Message Agent in previous releases.

#### Associated Files

The following files and publications are included in the release.

- interact\_e1\_mfp-3.3.4.fls
  - The Interact for Lexmark application for eSF v1.x printers
- interact\_e2\_mfp-3.3.4.fls
  - The Interact for Lexmark application for eSF v2.x printers
- interact\_e3-4\_s2-3.6.0.fls
  - The Interact for Lexmark application for eSF v3.x printers and eSF v4.x printers with 7- or 10-inch control panels
- interact e4 s3-3.6.0.fls
  - The Interact for Lexmark application for eSF v4.x printers with 4.3-inch control panels

### Requirements

The following software is required to implement Interact for Lexmark.

- Perceptive Content
- Perceptive Integration Server
- Required Licensing

### **Device Support**

You must install a printer that supports eSF applications.

- Supported eSF v1.x printers include:
  - X644e, X646e, X646dte Required firmware level: LC2.MC.P307aS1 or later.
  - X646ef Required firmware level: LC2.TI.P305aS1 or later.
  - X782e Required firmware level: LC2.TO.P305cS1 or later.

- X85x Required firmware level: LC4.BE.P457S1 or later.
- X94x Required firmware level: LC.BR.P051HDS1 or later.
- Supported eSF v2.x printers include:
  - X65x Required firmware level: LR.MN.P631 or later.
  - X73x Required firmware level: LR.FL.P631 or later.
  - X46x Required firmware level: LR.BS.P631 or later.
  - X86x Required firmware level: LP.SP.P631 or later.
- Supported eSF v3.x printers include:
  - X548x Required firmware level: LHS23.VK.P213a or later.
  - X74x Required firmware level: LHSC3.NY.P213a or later.
  - X792x Required firmware level: LHS23.MR.P213a or later.
  - X925x Required firmware level: LHS23.HK.P213a or later.
  - X95x Required firmware level: LHS23.TQ.P213a or later.
  - 6500e Required firmware level: LHS23.JR.P213a or later.
- Supported eSF v4.x printers include:
  - CX410, CX510 Required firmware level: LW30.GM.P436 or later.
  - MX410, MX510, MX511 Required firmware level: LW40.SB4.P436 or later.
  - MX610, MX611 Required firmware level: LW40.SB7.P436 or later.
  - MX710, MX711 Required firmware level: LW40.TU.P436 or later.
  - MX810, MX811, MX812 Required firmware level: LW40.TU.P436 or later.
  - MX6500e Required firmware level: LW40.JD.P436 or later.
  - MX910, MX911, MX912 Required firmware level: LF.MG.P053 or later.
- Memory: The printer must have 256MB of RAM; 1GB of RAM highly recommended for use with the Color TIFF feature.
- Hard Drive: The printer must have a hard drive installed to perform custom jobs and use the Color TIFF feature.